

Annexure D

BUILDING SAFETY CERTIFICATE

No. 124 /RED/NBC/2025-26

Dated: 28/03/2026

It is certified that the existing building **ST. GOPAL PUBLIC SCHOOL**, (name of the building or premises) at **SHYAMON, BARULI AHIR, AGRA, U.P** (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in School	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	3	-	-	-	-	-

The building is owned/occupied by building **ST. GOPAL PUBLIC SCHOOL**, (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the EXECUTIVE ENGINEER RURAL ENGINEERING DEPARTMENT (UP.Govt) (Name of Department/ Govt.) on 28-03-2026 (date of inspection) in the presence of **Mr. DAYASHANKAR** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 28-03-2026 for a period of 2 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Not Applicable
2. Not Applicable
3. Not Applicable
4. Not Applicable

Issued on 28-03-2026 at **Agra** by **RURAL ENGINEERING DEPARTMENT, AGRA**

Signature with Seal :


सहायक अभियन्ता
ग्रामीण अभियन्तन विभाग
प्रखण्ड-आगरा

Name : RADHA RAMAN SHARMA

Designation : ASSISTANT ENGINEER

Name & Address of Department/ Office: OFFICE OF EXECUTIVE ENGINEER

RURAL ENGINEERING DEPARTMENT
DIVISION AGRA